

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L40	1641	((temperature or thermal) near (exceed\$ or threhsold or overload\$ or maximum)) with (indicat\$ or alarm\$ or warn\$ or alert\$).detd.	USPAT	OR	OFF	2005/03/19 18:24
L41	1	40 and ((detect\$ or monitor\$ or sens\$) near lambda).detd.	USPAT	OR	OFF	2005/03/19 18:27
L42	0	40 and ((vehicle or car or automobile) with lambda).detd.	USPAT	OR	OFF	2005/03/19 18:27
L43	0	40 and ((vehicle or car or automobile) same lambda).detd.	USPAT	OR	OFF	2005/03/19 18:27
L44	966	((detect\$ or monitor\$ or sens\$) near lambda).detd.	USPAT	OR	OFF	2005/03/19 18:29
L45	23	44 and ((alarm\$ or indicat\$ or alert\$ ro warn\$) near lambda).detd.	USPAT	OR	OFF	2005/03/19 18:36
L46	905	(indicator\$ with chang\$ with (heat or temperature)).detd.	USPAT	OR	OFF	2005/03/19 18:36
L47	83620	"340"/\$.ccls.	USPAT	OR	OFF	2005/03/19 18:37
L48	48	46 and 47	USPAT	OR	OFF	2005/03/19 18:48
L49	23	("4371827").URPN.	USPAT	OR	OFF	2005/03/19 18:47
L50	14439	(material with chang\$ with (heat or temperature or thermal)).detd.	USPAT	OR	OFF	2005/03/19 18:49
L51	1478	50 and ((indicat\$ or warn\$ or alert\$ or alarm\$) near2 (heat or thermal or temperature)).detd.	USPAT	OR	OFF	2005/03/19 18:53
L52	19	51 and ((indicat\$ or warn\$ or alert\$ or alarm\$) with (screw or nut)).detd.	USPAT	OR	OFF	2005/03/19 18:52
L53	491	50 and ((indicat\$ or material) with (screw or nut)).detd.	USPAT	OR	OFF	2005/03/19 18:53
L54	49	53 and 51	USPAT	OR	OFF	2005/03/19 18:53
L55	31	54 not 52	USPAT	OR	OFF	2005/03/19 19:01
L56	24	("2870316"   "3802945"   "3822594"   "3959787"   "3965742"   "4102200"   "4189942"   "4351996"   "4649854"   "4682857"   "4738549"   "4751912"   "4806858"   "4983810"   "5315956"   "5482373"   "5499597"   "5543246"   "5750959"   "5767489"   "5786578"   "5997964"   "6104007").PN,	US-PGPUB; USPAT; USOCR	OR	OFF	2005/03/19 18:57
L57	120	(219/445.1).CCLS.	USPAT	OR	OFF	2005/03/19 19:04
L58	13794	"374"/\$.ccls.	USPAT	OR	OFF	2005/03/19 19:04

L59	5332	58 and (indicat\$ or alarm\$ or warn\$ or alert\$ or (chang\$ near color\$1)).detd.	USPAT	OR	OFF	2005/03/19 19:16
L60	366	59 and (vehicle or car or automobile).detd.	USPAT	OR	OFF	2005/03/19 19:06
L61	12	60 and lambda.detd.	USPAT	OR	OFF	2005/03/19 19:06
L62	17	("4501145").URPN.	USPAT	OR	OFF	2005/03/19 19:13
L63	7	("4658632").URPN.	USPAT	OR	OFF	2005/03/19 19:15
L64	112608	"73"/\$.ccis.	USPAT	OR	OFF	2005/03/19 19:15
L65	4655	64 and ((indicat\$ or alarm\$ or warn\$ or alert\$ or (chang\$ near color\$1)) with (temperature or thermal or heat)).detd.	USPAT	OR	OFF	2005/03/19 19:16
L66	20	65 and ((temperature or heat or thermal) near2 lambda).detd.	USPAT	OR	OFF	2005/03/19 19:16
L67	17	66 not 61	USPAT	OR	OFF	2005/03/19 19:23
L68	1154	(46 or 58 or 64) and (((thermal or heat or temperature) with (indicat\$ or sens\$ or alarm\$ or warn\$ or alert\$)) and (material with (chang\$ or melt\$) with (thermal or heat or temperature))).detd.	USPAT	OR	OFF	2005/03/19 19:25
L69	14	68 and ((oxidation or oxidiz\$) and (chemical near chang\$)).detd.	USPAT	OR	OFF	2005/03/19 19:26
L70	29	68 and ((oxidation or oxidiz\$) and (chemical near (chang\$ or reaction))).detd.	USPAT	OR	OFF	2005/03/19 19:28
L71	7	70 and alloy	USPAT	OR	OFF	2005/03/19 19:27
L72	2	71 and ceramic	USPAT	OR	OFF	2005/03/19 19:27
L73	181	68 and (oxidation or oxidiz\$ or (chemical near (chang\$ or reaction))).detd.	USPAT	OR	OFF	2005/03/19 19:28
L74	24	73 and (vehicle or car or automobile).detd.	USPAT	OR	OFF	2005/03/19 19:29